CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : **Improvements and Development of school building at Jalahalli in ward No.16, BBMP, Bangalore.**

Name of Client	:	**Executive Engineer,** RR Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. K Damodar & Co,** Contractor, Bangalore.
Total Cost	:	Rs. 183.54 Lakhs
Date of Inspection	:	04.07.2022
Status of Bill	:	2nd and Final Bill
Work Order No.	:	EE/RRND/Wo.No/000060/2021-22
In the Presence of	:	(a) **Assistant Engineer (W. No.16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Sl.No	Description of the Item		Unit	Qty	Comments / observations
1	KSRRB M200-12.1. Dismantling of existing structures like culverts,		cum	181.7	Work done up to the billed quantity and Quality is satisfactory
2	KSRRB M200-14.1. Dismantling of existing	:	cum	197.34	Work done up to the billed quantity and Quality is satisfactory
3	KSRB 200-7.1 : Clearing grass and removal of rubbish	:	HA	0.15	Work done up to the billed quantity and Quality is satisfactory
4	KSRB 2-2.1 Earth work excavation for foundation of	:	cum	866.59	Work done up to the billed quantity and Quality is satisfactory
5	KSRB-3.2 : Providing and injecting chemical emulsion	:	Sqm	811.32	Work done up to the billed quantity and Quality is satisfactory
7	KSRB 4-1.2 Providing and Laying in position plain	:	cum	119.55	Work done up to the billed quantity and Quality is satisfactory
8	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	164.85	Work done up to the billed quantity and Quality is satisfactory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

Sl.No	Description of the Item		Unit	Qty	Comments / observations
9	KSRB 4-6.1 : Providing and removing a centering,	:	Sqm	269.4	Work done up to the billed quantity and Quality is satisfactory
11	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	42.07	Work done up to the billed quantity and Quality is satisfactory
12	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	25.12	Work done up to the billed quantity and Quality is satisfactory
13	KSRB 4-6.5: Providing and removing centering,	:	Sqm	478.98	Work done up to the billed quantity and Quality is satisfactory
14	KSRB 4-6.5: Providing and removing centering,	:	Sqm	258.48	Work done up to the billed quantity and Quality is satisfactory
15	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	28.84	Work done up to the billed quantity and Quality is satisfactory
16	KSRB 4-6.5: Providing and removing centering,	:	Sqm	283.03	Work done up to the billed quantity and Quality is satisfactory
17	ksrb 5.2-3 Providing and constructing grinite	:	cum	56.27	Work done up to the billed quantity and Quality is satisfactory
19	KSRB 5.3-3 : Providing and constructing granite / trap /	:	cum	21.44	Work done up to the billed quantity and Quality is satisfactory
21	KSRB-15.2.2 Providing ruled pointing to coursed stone	:	Sqm	47.64	Work done up to the billed quantity and Quality is satisfactory
22	KSRB 2.3 : Filling available excavated earth (excluded	:	cum	582.19	Work done up to the billed quantity and Quality is satisfactory
24	KSRB 5-14.1 : Providing and constructing percast concrete	:	Sqm	34.43	Work done up to the billed quantity and Quality is satisfactory
26	KSRB 5-14.1 : Providing and constructing percast concrete	:	Sqm	26.55	Work done up to the billed quantity and Quality is satisfactory
28	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	2.97	Work done up to the billed quantity and Quality is satisfactory
29	KSRB 4.2.7 : Providing and laying in position reinforced	:	cum	2.98	Work done up to the billed quantity and Quality is satisfactory
30	KSRB 4-6.7: Providing and removing centering,	:	Sqm	49.42	Work done up to the billed quantity and Quality is satisfactory
31	KSRB 4-6.7: Providing and removing centering,	:	Sqm	50.48	Work done up to the billed quantity and Quality is satisfactory

Scanned with CamScanner

Sl.No	Description of the Item		Unit	Qty	Comments / observations
32	KSRB 4.2.11 : Providing and laying in position reinforced	:	Sqm	40.86	Work done up to the billed quantity and Quality is satisfactory
33	KSRB 4.2.11 : Providing and laying in position reinforced	:	Sqm	43.74	Work done up to the billed quantity and Quality is satisfactory
34	KSRB 4-6.10: Providing and removing centering,	:	Sqm	40.86	Work done up to the billed quantity and Quality is satisfactory
35	KSRB 4-6.10: Providing and removing centering,	:	Sqm	43.74	Work done up to the billed quantity and Quality is satisfactory
36	KSRB 4-6.7: Providing and removing centering,	:	Sqm	333.41	Work done up to the billed quantity and Quality is satisfactory
37	KSRB 4-6.7: Providing and removing centering,	:	Sqm	333.41	Work done up to the billed quantity and Quality is satisfactory
38	KSRB 4-6.7: Providing and removing centering,	:	Sqm	36.52	Work done up to the billed quantity and Quality is satisfactory
39	Providing and laying cement concrete using 20mm down	:	cum	101.79	Work done up to the billed quantity and Quality is satisfactory
41	Providing and laying cement concrete using 20mm down	:	cum	107.37	Work done up to the billed quantity and Quality is satisfactory
43	Providing and laying cement concrete using 20mm down	:	cum	6.83	Work done up to the billed quantity and Quality is satisfactory
45	KSRB 4-6.3: Providing and removing centering,	:	Sqm	678.6	Work done up to the billed quantity and Quality is satisfactory
46	KSRB 4-6.3: Providing and removing centering,	:	Sqm	715.78	Work done up to the billed quantity and Quality is satisfactory
47	KSRB 4-6.3: Providing and removing centering,	:	Sqm	45.54	Work done up to the billed quantity and Quality is satisfactory
49	KSRB 15.3.13 Providing 12mm thick cement	:	Sqm	720	Work done up to the billed quantity and Quality is satisfactory
50	KSRB 15.3.13 Providing 12mm thick cement	:	Sqm	757.18	Work done up to the billed quantity and Quality is satisfactory
51	KSRB 7.9 : Providing and fixing M.S. grill work for	:	Kg	1634.9	Work done up to the billed quantity and Quality is satisfactory
52	KSRB 7.9 : Providing and fixing M.S. grill work for	:	Kg	1729.4	Work done up to the billed quantity and Quality is satisfactory

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited
Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item		Unit	Qty	Comments / observations
53	KSRB15-3.6 : Providing 15 mm thick cement plaster in	:	Sqm	1319.7	Work done up to the billed quantity and Quality is satisfactory
54	KSRB15-3.6 : Providing 15 mm thick cement plaster in	:	Sqm	1329.6	Work done up to the billed quantity and Quality is satisfactory
55	KSRB 15-7: Providing lime rendering for plastering to	:	Sqm	1319.7	Work done up to the billed quantity and Quality is satisfactory
56	KSRB 15-7: Providing lime rendering for plastering to	:	Sqm	1329.6	Work done up to the billed quantity and Quality is satisfactory
57	KSRB 15-7: Providing lime rendering for plastering to	:	Sqm	343.88	Work done up to the billed quantity and Quality is satisfactory
59	KSRB 15-7: Providing lime rendering for plastering to	:	Sqm	320.69	Work done up to the billed quantity and Quality is satisfactory
61	KSRB 4.9.2: Providing T.M.T steel reinforcement for R.C.C work including	:	Tonne	56.46	Work done up to the billed quantity and Quality is satisfactory
62	Providing Honne wood frames of doors, windows,	:	cum	0.83	Work done up to the billed quantity and Quality is satisfactory
63	Providing Honne wood frames of doors, windows,	:	cum	0.83	Work done up to the billed quantity and Quality is satisfactory
64	Providing and filling in foundation / below flooring	:	cum	67.5	Work done up to the billed quantity and Quality is satisfactory
65	Geophysical investigation of site for Sinking borewell for	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
66	Sinking borewell of 165 mm dia clear using super fast	:	Sqm	50	Work done up to the billed quantity and Quality is satisfactory
67	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
68	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300		Rmt	50	Work done up to the billed quantity and Quality is satisfactory
69	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
70	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

Sl.No	Description of the Item		Unit	Qty	Comments / observations
71	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
72	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
73	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
74	Sinking borewell of 165 mm dia clear using super fast	:	Rmt	20	Work done up to the billed quantity and Quality is satisfactory
75	Providing and fixing 250mm dia PVC (casing pipe) (page	:	Rmt	12	Work done up to the billed quantity and Quality is satisfactory
76	Supply of ISI Mark 175mm nominal Bore, Plain end steel	:	Rmt	50	Work done up to the billed quantity and Quality is satisfactory
77	Providing 175mm Dia M.S. Collar (P.No.iii,I.No.86)	:	Nos	8.33	Work done up to the billed quantity and Quality is satisfactory
78	Providing 175mm dia Bore Cap CE (M)	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
79	Atalanta suguna CRI KIRLOSKAR and other	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
80	Providing and fixing in trenches galvinised/mild steel	:	Rmt	370	Work done up to the billed quantity and Quality is satisfactory
81	Supplying and drawing 3 core flat PVC sheathed	:	Rmt	750	Work done up to the billed quantity and Quality is satisfactory
82	Providing and fixing in position 50mm Nominal	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
83	Spplying and fixing 50mm GI Union.(PWD SR 2018-	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
84	Spplying and fixing 50mm GI Elbow.(PWD SR 2018-	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
85	Spplying and fixing 50mm GI Nipple.(PWD SR 2018-	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
86	Spplying and fixing 50mm GI Hose colleres(PWD SR	:	Nos	62	Work done up to the billed quantity and Quality is satisfactory
87	Supplying and fixing 20" x 20" x 2.5" polished wood	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory

QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item		Unit	Qty	Comments / observations
88	Supplying and fixing miniature circuit breakers on	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
89	Supplying of TPST with rewirable porcelain channels	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
90	Supplying and fixing LED type panel board indicating	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
91	Suppling fully automatic star delta starter unit push button	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
92	Supplying and fixing single phase preventer using	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
93	Wiring for lighting/power circuit using one of FRLS	:	Mtrs	20	Work done up to the billed quantity and Quality is satisfactory
94	Supplying fixing and wiring heavy duty low voltage	:	Nos	4	Work done up to the billed quantity and Quality is satisfactory
95	Supplying, fixing, wiring, earth electrode for grounding	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
96	Digging of trench of 0.36mtrs deepx0.5 mtrs wide	:	Mtrs	8	Work done up to the billed quantity and Quality is satisfactory
97	Supplying laying 1.1 KV class LT UG cable having	:	Mtrs	10	Work done up to the billed quantity and Quality is satisfactory
98	Labour charge for laying 1.1 KV class UG cable in	:	Nos	25	Work done up to the billed quantity and Quality is satisfactory
99	Supplying and fixing class-A(medium duty) GI pipe	:	Rmt	2	Work done up to the billed quantity and Quality is satisfactory
100	Supplying and fixing LT cast iron pot heads suitable for	:	Nos	1	Work done up to the billed quantity and Quality is satisfactory
101	Supplying and fixing porcelain fuse channel with	:	Nos	3	Work done up to the billed quantity and Quality is satisfactory
102	Concealed Conduit System Supplying heavy gauge PVC	:	Mtrs		Work done up to the billed quantity and Quality is satisfactory
103	19/20mm Dia 2mm thick	:	Mtr	250.00	Work done up to the billed quantity and Quality is satisfactory
104	25mmdia 2mm thick	:	Mtr	500.00	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

CIVIL QUALITY
CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited
Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item		Unit	Qty	Comments / observations
105	Groove Cutting in Walls Supplying heavy gauge PVC	:	Mtrs		Work done up to the billed quantity and Quality is satisfactory
106	19/20mm Dia 2mm thick	:	Mtr	230.00	Work done up to the billed quantity and Quality is satisfactory
107	25mmdia 2mm thick	:	Mtr	120.00	Work done up to the billed quantity and Quality is satisfactory
108	Supplying And Fixing Metal Fan Box with Round Hook.	:	No	36.00	Work done up to the billed quantity and Quality is satisfactory
109	KSRB 9-27.1 : Fixing of door frame in an existing opening	:	Nos	21.00	Work done up to the billed quantity and Quality is satisfactory
110	KSRB 15.9 Providing and fixing Corner beads	:	Mtrs	816.48	Work done up to the billed quantity and Quality is satisfactory
111	KSRB 15.8.2 Providing and fixing plaster mesh 150mm	:	Mtrs	298.08	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner